



# ANT11TS33MxIB Module Errata

D00001453 Rev1.0

## Copyright Information and Usage Notice

This information disclosed herein is the exclusive property of Dynastream Innovations Inc. No part of this publication may be reproduced or transmitted in any form or by any means including electronic storage, reproduction, execution or transmission without the prior written consent of Dynastream Innovations Inc. The recipient of this document by its retention and use agrees to respect the copyright of the information contained herein.

The information contained in this document is subject to change without notice and should not be construed as a commitment by Dynastream Innovations Inc. unless such commitment is expressly given in a covering document.

The Dynastream Innovations Inc. ANT Products described by the information in this document are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Dynastream product could create a situation where personal injury or death may occur. If you use the Products for such unintended and unauthorized applications, you do so at your own risk and you shall indemnify and hold Dynastream and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Dynastream was negligent regarding the design or manufacture of the Product.

©2011 Dynastream Innovations Inc. All Rights Reserved.

## Table of Contents

<b>1</b>	<b>Module Revision .....</b>	<b>4</b>
1.1	Production Tracking Code.....	4
1.2	Version String .....	4
<b>2</b>	<b>Known Issues .....</b>	<b>4</b>
2.1	Multiple Channel Collision .....	4

This document describes the known operation exceptions to ANT11TS33MxIB module. Workarounds or fixes are provided.

## 1 Module Revision

The Module revision refers can be identified in the following ways.

### 1.1 Production Tracking Code

Each ANT11TS33MxIB module has a tracking code printed on the product sticker. The last character denotes the revision. The picture shows that the ANT11TS33M5IB is rev A.



### 1.2 Version String

In the case that the product sticker is hard to access or identification marker is blurred, an ANT version command 0x3E can be issued via the serial communication to acquire the version String.

Revision	Version String
C	AGC1.05RAA <sup>1</sup>
A/B	AGC1.01RAA <sup>1</sup>

Note 1: "RAA" denotes this AT3 module is ANT11TS33MxIB.

## 2 Known Issues

### 2.1 Multiple Channel Collision

Rev A and B are affected. This issue has been fixed in rev C

#### Symptoms:

Having multiple channels on a single device with at least one master can cause prolonged blocked channel events and in some cases a channel outage of 2 seconds or more resulting in long data outages or searches on the slave device.

#### Conditions:

Channels of different message rates are opened on the same device, one being a master channel. The message rates are not synchronous relative to each other and thus collide over time.

#### Consequences:

Channel collision is unavoidable in this case of multiple channels at different message rate. But the issue causes higher than normal failures. In some instances, this causes a 2 second outage for a master channel, which can result in the slave device dropping to search.

**Workaround:**

If the multi-channel scenario is one master and some number of slaves, using channel 0 for the master channel can mitigate the issue.